Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: RIDL 34-12 TFH CTB

Field Name: ZENITH Well File #:

 Date Incident:
 3/26/2015
 Time Incident:
 08:45
 Facility ID Number:
 220796-01

 County:
 STARK
 Twp:
 139
 Rng:
 99
 Sec:
 12
 Qtr:
 SW SE

Location Description:

Submitted By: Allison Christensen Received By:

Contact Person: Allison Christensen

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.8 Mile

Distance Nearest Water Well: Type of Incident: Pump Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 110 Barrels 95 Barrels 110 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/6/2015 Clean Up Concluded: 4/1/2015

Risk Evaluation:
None noted

Areal Extent:

NA

Potential Environmental Impacts:

None noted

Action Taken or Planned:

A vac truck was called to location and the seal was replaced on the pump. Future plans are to remove effected soil and take to an approved disposal.

Wastes Disposal Location: To an approved disposal

Agencies Involved: BLM

Updates

Date: 3/27/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.